

ਵੱਲੋਂ,

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਲੇ. ਨਿ. ਵਿ. ਭ ਤੇ ਮ ਸਾਖਾ,
ਲਹਿਰਾਗਾਗਾ।

ਵੱਲੋਂ,

ਪ੍ਰਿੰਸੀਪਲ,
ਗਿਆਨ ਗੰਗਾ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ,
ਬੱਲਰਾਂ, ਸੰਗਰੂਰ।

ਨੰ. 240

ਮਿਤੀ. 24/3/2026

ਵਿਸ਼:-

ਬਿਲਡਿੰਗ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ। (ਗਿਆਨ ਗੰਗਾ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ, ਬੱਲਰਾਂ ਸੰਗਰੂਰ)

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਗਈ ਹੈ ਕਿ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਗਰਾਊਂਡ ਅਤੇ ਫਸਟ ਫਲੋਰ ਹਨ। ਜਿਸ ਦੇ ਗਰਾਊਂਡ ਫਲੋਰ ਵਿੱਚ 25 ਕਮਰੇ, 3 ਹਾਲ ਹਨ ਅਤੇ ਫਸਟ ਫਲੋਰ ਵਿੱਚ 28 ਕਮਰੇ ਅਤੇ 1 ਹਾਲ ਹੈ। ਇਹ ਇਮਾਰਤ ਨੌਥੀ ਨਕਸ਼ੇ ਅਨੁਸਾਰ ਬਣੀ ਹੋਈ ਹੈ। ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵੀ ਡਿਫੈਕਟ ਨਹੀਂ ਹੈ। ਇਹ ਇਮਾਰਤ ਦੇਖਣ ਨੂੰ ਸੋਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿੱਚ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ, ਕੁਦਰਤੀ ਆਫਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਂਹ ਬਰਿੰਦੀਆਂ ਹਨ, ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਈ ਚਲਾਨ ਰਸੀਦ ਨੰਬਰ 23554741 ਮਿਤੀ 21-05-2026 ਰਾਹੀਂ 15000 ਰੁਪਏ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਏ ਗਏ ਹਨ।

ਇਸ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ 31-03-2027 ਤੱਕ ਹੈ।

ਨੌਥੀ/ ਸੇਫਟੀ ਰਿਪੋਰਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਲੇ. ਨਿ. ਵਿ.
ਭ ਤੇ ਮ ਸਾਖਾ, ਲਹਿਰਾਗਾਗਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ.

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਮੰਡਲ, ਲੇ. ਨਿ. ਵਿ., ਭ ਤੇ ਮ ਸਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ. 1150 ਮਿਤੀ 04.05.2026 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਨੌਥੀ/ ਈ-ਰਸੀਦ ਨੰਬਰ 23554741

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਲੇ. ਨਿ. ਵਿ.
ਭ ਤੇ ਮ ਸਾਖਾ, ਲਹਿਰਾਗਾਗਾ।

Building Safety Report

Name of School:- Gyan Ganga International School, Balran,(Sangrur)

I have visited the above mentioned school building along with
Sh. Manish Kumar JE on 20-05-2026 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications. Test Reports of Material used Quality Control reports and certificate from Engineer in Charge for construction are not available.
- b) In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e) A separate certificate regard Electrical Works should be obtained from the competent authority.
- f) The owner of the building/ Management is fully responsible regarding safety of building from all angels in spite of this report.
- g) The covered area of the building is 56907 Sq.ft.
- h) This Report is not valid for legal purpose.
- i) This building visually seems safe to occupy for the normal use up to: 31-03-2027
- j) The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as per Government policy No. 05/13/2018-3BR3/1294287/3 dated 10-08-2018.


Sub Divisional Engineer,
Construction Sub Division,
PWD B&R, Lehragaga. 