

ਵਲੋ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲਹਿਰਾਗਾਗਾ।

ਵਲ


ਪ੍ਰਿਸੀਪਲ,
ਗਿਆਨ ਰੰਗਾ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ,
ਬਲਰਾਂ ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ।

ਨੰ: 10

ਮਿਤੀ: 19-04-2023

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ।
ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਆਪ ਦੀ ਮੰਗ ਅਨੁਸਾਰ ਕਾਲਜ ਦੀ ਬਿਲਡਿੰਗ ਸਬੰਧੀ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ
ਨਿਰਧਾਰਿਤ ਪ੍ਰੋਫਾਡਮੇ ਤੇ ਆਪ ਨੂੰ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਫੀਸ ਜੀ. ਆਰ. ਨੰ:.....ਮਿਤੀ.....
ਰਾਹੀ ਪ੍ਰਾਪਤ ਕੀਤੀ।

ਨੱਥੀ/ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ
ਲਹਿਰਾਗਾਗਾ।

ਮਿਤੀ:-

ਪਿਠ ਅੰਕਣ ਨੰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਨੂੰ ਉਹਨਾ ਦੇ
ਪੱਤਰ ਨੰ: 142 ਮਿਤੀ 11-04-2023 ਦੇ ਸਬੰਧ ਵਿਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।


↑
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲਹਿਰਾਗਾਗਾ।

Building Safety Report

Name of School:- Gyan Ganga International School Village Balran, Tehsil Lehra
District Sangrur

I have visited the above mentioned school building along with Sh Megh Raj AE on 19-04-2023 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and certificate from Engineer in Charge for construction are not available.
- b) In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e) A separate certificate regard Electrical Works should be obtained from the competent authority.
- f) The owner of the building/ Management is fully responsible regarding safety of building from all angels in spite of this report.
- g) The covered area of the building is 56907 Sq.ft.
- h) This Report is not valid for legal purpose.
- i) This building visually seems safe to occupy for the normal use up to: 31-03-2024


Sub-Divisional Engineer
Const. Sub-Divn. PWD B&R
Lehragada